## STERLING ELECTRONIC DIGITALSCALE **USER MANUAL**

 $\begin{array}{ll} \mbox{Thanks for choosing our digital counting scale which Is easy to operate. Please read the user} \\ \mbox{Power Control} & \mbox{Auto power oft after $1$ minute without operation (set up $1$ } \end{array}$ 

Switchon/off: Working temperature: LCD display

I Q.JQ°C 5-digit LCD display White Alkaline Battery AAA x2 Back light Power Supply

Measure 95.6G 62.2X53.7mm Weight Salver Size

116X64X17mm

Weight 95.6G
Salver Size 62.2X53.7mm

Tare
Counting
Low Power
Unit Switch gloz/oz/dwt/ct/11/gn

II. Operation
Put 2xAAA battery into the battery room of the scale Place the scale on a solid and flat board without wind and vibrancy
1. Press the button \*\*ONOFF\*\* \*\*O. O\* or 0.00\* is displayed in 3 seconds.
2. Put the article on the scale. The Unit code is blinking when it has not been steady: You can read the weight when the unit code stops blinking.
3. Press the button \*\*ONOFF\*\* \*\*O force to the nulling operation
5. Press the button \*\*ONOFF\*\* to force to the nulling operation
5. Press the button \*\*ONOFF\*\* to force to the nulling operation
6. Press the button \*\*ONOFF\*\* to turn off the scale at working status 7.
Calibrating Operation
Press the button \*\*ONOFF\*\* press down UNIT key and don't put after switch on. Showing Io hold will appear CAL\*\* Click the UNIT key once again, showing to hold will show a weights(500G); Pull up to should the code, after 5 second, showing to hold will show PASS; Revise be over at this time. (You should calibrate the scale when the temperature change or other reasons).
8. How to operate Counting Function
Please prepare ZS.05,75 or 100 pieces of samples. When the scale is ready to weight goods, place the samples on the scale, then you can see the weight. Please prepare ZS.05,75 or 100 pieces of samples. When the screen shows a quantity you can press the button \*\*UNIT\*\* or select a right quantity-2-5,075 or 100 pieces. Inally, press the button \*\*PCS\*\* for confirmation this time, the screen displays the quantity. You con press the button \*\*ONOFF\*\*. The north of the press of the pres

- youds. Pre:

- youd 3000G/0. I 15000CT/0.5 96.480 Ol/0.01 1929.2DWT/0.1 80.00TLJ0.005 16.07540ZT/O. OI 98.452OZT/0.0I

- TROY QUINEE(QZT) 9.6452QZT/0.01 16.0754QZT/0.01 98.452QZT/0.01 Attention:

  ® Place the scale on a solid and flat board without wind and vibrancy

  ® Place the scale on a solid and flat board without wind and vibrancy

  ® Do not over load, otherwise the sensor will be damaged; Do not bump the scaler when you put the article on the scale, place it carefully

  ® Keep away from mobile phones over 50cm

  ® Read the weight after the unit code stops blinking.

  ® Replace batteries when II shows low power

  ® Working temperature 0-30°C. Please calibrate thescale if the temperature Istoo low/high. Please place the scale in 30 minutes first, let the temperate beeven, then make the calibration

  ® The screen display Full. When It is overweight

  Please do not disassemble! Careful storage!