USER MANUAL

OP-931 Series

Mini Crane Scale

List

Security Guide	1
1. Instruction	1
1.1 Function feature	1
1.2 Specification	2
1.3 Battery instruction	2
2 specification	2
2.1 Model & specification	2
2.2 Installation	3
3、Basic operation	4
3.1 Key function	4
3.2 Power on	4
3.3 Power off	5
3.4 Zero/tare	5
3.5 Hold function	6
3.6 Units conversion	6
4、Parameter setting	8
5 Packing list	9

Security Guide

In order to ensure the accuracy of crane scale, please pay attention to the daily use and maintenance:

- Don't overload, or it will damage the load cell, even worse causing casualties.
- Don't hang the heavy weight on the crane scale, or it will reduce the accuracy, and short the usage life of load cell.
- Please check the hook and ring before using.
- Please check the power frequently; When the crane scale is Low-voltage, please change the battery.
- Please take out the battery if no long-term using.
- Don't use the crane scale in thunderstorm environment.
- Don't repair by yourself, please contact with your local dealer.

1 Instruction

1.1 Function feature

- Light, handy and portable
- Low power design, longer battery usage time
- Perfect function:

 $\label{low-battery} \mbox{Low-battery detection and warning, shutdown automatically while under voltage Hold function, lock the weight}$

Idle mode and Automatic power off function

Zero/tare function

1.2 Specification

Accuracy class

Tare range 2%~100% max. Capacity

Initial zero range ±10% max. Capacity

Manually zero range ±2% max. Capacity

Operation temperature& humidity -10~+40°C; ≤90%RH

Storage temperature -40~+70 °C

1.3 Battery instruction

The crane scale use 3 pcs of 7# AAA battery and work about 50 hours. If close the backlight mode, the battery can last 80 hours. When Low-battery detection and warns (light up the low battery icon), please change the battery. If not timely change, the crane scale will shutdown automatically.

(III)

2, specification

2.1 Model & specification

Product No.	Model	Maximum Capacity	Division	Outline size W*L*H	Net weight
		(kg)	(kg)	(mm*mm*mm)	(kg)
OP-931-003	OCS-M1-003	30	0.01	88*46*268	0.6
OP-931-006	OCS-M1-006	60	0.02	88*46*268	0.6
OP-931-010	OCS-M1-010	100	0.05	88*46*268	0.6
OP-931-015	OCS-M1-015	150	0.05	88*46*268	0.6
OP-931-020	OCS-M1-020	200	0.1	88*46*268	0.6
OP-931-030	OCS-M1-030	300	0.1	88*46*268	0.6

2.2 Installation

Put in 3 pcs of 7# AAA battery, and hang on the hook before using.



3. Basic operation


3.1 Key function

Key /function	Weighing mode	Veighing mode Parameter setting	
O	Power on/off	Power on/off Exit	
HOLD UNIT	Hold/units conversion	Confirm	
TARE ZERO	Zero/tare	Page down	


3.2 Power on



Press 1 second, power On Self Test.



If exceed the zero range, it displays [ERR6], or goes to weighing zero.



3.3 Power off

Press 1 second, the crane scale will power off.

If the battery under voltage, the crane scale power off automatically.

If there is no operation in 10 minutes, the crane scale power off automatically.


3.4 Zero/tare

While the weight is stable and exceed the zero range, press $\frac{TARE}{ZERO}$ to enter into net weight mode, then the current weight tare as tare weight, display the net weight

TARE

zero; While the weight is stable and in the zero range, press $\overline{\text{ZERO}}$, back to gross weight mode, display gross weight zero.

Tare:



Zero:



3.5 Hold function


HOLD

While setting Hold=1, press UNIT ,realize peak hold function.

HOLD

While setting Hold=2, press $\overline{\text{UNIT}}$, hold the current weight 15 seconds; Press HOLD

UNIT , release hold function.



HOLD UNIT



While setting Hold=3, the weight is stable and hold the current weight 15

HOLD

seconds; Press UNIT, release hold function.


Hold time can be setting in Ht parameter.

3.6 Units conversion

HOLD


Press UNIT 1 second, the units conversion between kg/lb/N.

See No. 4 parameter setting (Units conversion: UnS).



HOLD UNIT









Note: the convert unit still saved after power off.

4. Parameter setting

Function	Display	Parameter instruction	
Automatic	oFF 10	=0 close this function	
power off		=10 power off in 10 minutes	
		=30 power off in 30 minutes	
		=60 power off in 60 minutes	
Back light Mode	BL 1	=0 close back light Mode	
		=1 auto back light	
		=2 normally on back light	
Units conversion	UnS 1	=0 close Units conversion	
		=1 kg/N conversion	
		=2 kg/lb conversion	
		=3 kg/lb/N conversion	
Hold function	Hold 2	=0 close hold function	
		=1 peak hold	
		=2 data Hold	
		=3 auto Hold	
Hold time	Ht 1	=0 no time limit	
		=1 15*1 second	
		=2 15*2 second	
		=3 15*3 second	
		=4 15*4 second	

Packing list

S/N	Product name	Qty.	Note
1	OP-931 Crane scale	1	
2	AAA Battery	3	
3	User manual	1	
4	certification	1	
5	Carton	1	

Version: 7652PCN031150716